

HONEYWELL TRACE™

R121 PATCH 2

Software Change Notice

HTDOC-X593-en-121 Patch 2

November 2018

DISCLAIMER

This document contains Honeywell proprietary information. Information contained herein is to be used solely for the purpose submitted, and no part of this document or its contents shall be reproduced, published, or disclosed to a third party without the express permission of Honeywell International Sàrl.

While this information is presented in good faith and believed to be accurate, Honeywell disclaims the implied warranties of merchantability and fitness for a purpose and makes no express warranties except as may be stated in its written agreement with and for its customer.

In no event is Honeywell liable to anyone for any direct, special, or consequential damages. The information and specifications in this document are subject to change without notice.

Copyright 2018- Honeywell International Sàrl

Table of contents

| | | |
|----------|---|-----------|
| 1 | ABOUT THIS DOCUMENT | 4 |
| 1.1 | Revision history | 4 |
| 2 | INSTALL R121 PATCH 2 | 5 |
| 3 | INSTALLING PATCH 2 ON TRACE REMOTE NODE..... | 7 |
| 4 | ISSUES RESOLVED | 14 |
| 4.1 | R121 Patch 2..... | 14 |
| 5 | JIRA PARs..... | 19 |
| 5.1 | Resolved PARs..... | 19 |
| 5.2 | Known Issues..... | 19 |
| 6 | SIEBEL PARs..... | 20 |
| 6.1 | Resolved PARs..... | 20 |
| 6.2 | Known Issues..... | 20 |
| 7 | NOTICES..... | 21 |

1 About this document

This Software Change Notice contains important information that must be read prior to installing and working with Honeywell Trace R121 Patch 2. It also contains known issues, documentation updates, and additional information.

1.1 Revision history

| Version | Release | Date | Description |
|---------|---------|---------------|--------------------------|
| A | R 121 | November 2018 | Updated for R121 Patch 2 |

2 Install R121 Patch 2

Install the cumulative patch **Trace_121.1.08.4_REV8** on Honeywell Trace Server (L3 and L3.5), Offline Data Collector, and remote nodes.

This patch is NOT applicable for:

- Experion Server node

| | |
|--|---|
|  NOTE | Trace remote node is not required to be installed on Experion Server for IAA report generation. |
|--|---|

| | |
|--|--|
|  NOTE | This is a cumulative patch and it is applicable on Trace_121.1.08.0_REV7 Base Media and Trace_121.1.08.4 Patch 2 |
|--|--|


| If installing on... | Follow these steps |
|---|--|
| Trace Server at L3 / Offline Trace Server | <ol style="list-style-type: none"> 1. Copy the update.exe from Trace_121.1.08.4_REV8\Patch\PT_Server\L3. 2. Stop the Honeywell LSS-PT Data Collection, Honeywell Data Synchronization, Honeywell Trace Workflow and License services. 3. Install the update.exe of patch Trace_121.1.08.4_REV8. 4. Start the Honeywell LSS-PT Data Collection, Honeywell Data Synchronization, Honeywell Trace Workflow and License services. If it does not start automatically after applying patch, then start it manually. |
| Trace Server at L3.5 / L4 | <ol style="list-style-type: none"> 1. Copy the update.exe from Trace_121.1.08.4_REV8\Patch\PT_Server\L4. 2. Stop the Honeywell Data Synchronization and License services. 3. Install the update.exe of patch Trace_121.1.08.4_REV8. 4. Start the Honeywell Data Synchronization, and License services. If it does not start automatically after applying patch, then start it manually. |

| | |
|------------------------|--|
| Trace remote node | <ol style="list-style-type: none">1. Install the HoneywellTraceinstallInvoker.exe of patch located in Trace_121.1.08.4_REV8\Patch\pt_remotenode <p>Note: HoneywellTraceinstallInvoker.exe patch is no longer applicable for Experion server.</p> |
| Offline data Collector | <ol style="list-style-type: none">1. Copy the update.exe from Trace_121.1.08.4_REV8\Patch\PT_Server\DM2. Install the update.exe of patch Trace_121.1.08.4_REV8. |


3 Installing Patch 2 on Trace Remote Node

To install Honeywell Trace Remote Node:


1. From the installation media, access the <drive>:\Setup\Packages\pt_remotenode folder. Right-click the **HoneywellTraceInstallInvoker.exe**, and select **Run as Administrator** to launch the installer. Acknowledge the confirmation message.



2. The installation wizard's **Welcome** screen appears. Click **Next** to continue.




3. On the **License** screen, select the **I accept the terms in the license agreement** option and click **Next**.



A screen appears where following message is received:

“Warning: Firewall Check – Firewall is disabled. Enable the firewall and retry.”


4. Click **Next**.



5. Configure the certificate by either:
 - a. Selecting an available certificate for HTTPS support from the drop-down list (Not applicable if using Windows XP).


Or

- b. Checking the **Create a self-signed certificate for Trace Remote Node** option.




- 6. Click **Next**.
- 7. On the **User Credentials** screen:
 - a. APPLICABLE ONLY IF INSTALLING ON Experion / FLEX / ES-C / EST / ESV / ESV-T.
 - Type the password for the user (IAA Service User) who collects System performance (IAA) data. This user must have Local Administrator privilege on Experion / FLEX / ES-C / EST / ESV / ESV-T.

| | |
|---|--|
|  ATTENTION | <p>If you want to add multiple users, use semicolon and one space to separate the user accounts. For example, enter DOMAIN\user1; DOMAIN\user2; DOMAIN\user3; DOMAIN\user4</p> |
|---|--|




8. Click **Next**. The installer validates if the given user has permission to collect data. An error message is shown if the given user does not have the required permission. Provide a user who has the required permission and click **Next**.
9. On the **Summary** screen, click **Install** to begin the installation.



Step Result: The installation begins and progress is shown.


| | |
|--|---|
|  NOTE | Typically, it takes about an hour for the installation to complete. |
|--|---|

10. The following window appears. Click **Add**.



11. In the ensuing dialog box, click **Add**; then **Locations** and select the domain/workgroup to which the Honeywell Trace server belongs.
12. Click **OK**.
13. In the **Select Users, Computers, Service, Accounts or Groups** dialog box, under **Enter the object names to select**, type *the same user name entered in step 6 of this procedure*.
14. Click **Check Names**. Ensure the user name you have provided is identified.
15. Click **OK**. Ensure that the user is listed under the **Group or user names**.


16. Click the user and check the **Execute (Invoke)** option for this user.



17. Click **Apply** and click **OK**.

| | |
|--|---|
|  NOTE | <p>If there are multiple agents on a single remote node, add multiple users and provide each with Read and Execute permissions.</p> |
|--|---|

18. After the installation is complete, click **Finish** on the **Completion** screen to close the installation wizard.



After completing this configuration, the administrator must apply a valid license and perform the post-installation tasks of configuring the Honeywell Trace server to enable data collection settings.

4 Issues Resolved

4.1 R121 Patch 2

The following is the list of resolved issues.

| JIRA/SIEBEL PAR Reference | Issue - Description/Recovery/Workaround | | |
|---------------------------------|--|--------------|--------------------------------|
| RTRACE-1049 | If there was a . (dot) in username, users were not able to login. | | |
| RTRACE-1309 | The single Shadow Server could not fetch data from multiple PHD buffers. | | |
| RTRACE-1310 | Users could not see device control (DEVCTL) point type connection for APM node. | | |
| RTRACE-1311 | Users could not see device control (DEVCTL) point type connection for HPM node. | | |
| RTRACE-1312 | TPS HPM and AM values were mismatching. Now, following parameters are corrected for the respective point types in those two nodes. | | |
| | Node | Point type | Parameters |
| | TPS HPM | Analog Input | PVEXEUHI, PVEXEULO, and PVHITP |
| | TPS HPM | DI | DLYTIME |
| | TPS HPM | DISOE | DLYTIME |
| | AM | REGCTL | PVEUHI |
| RTRACE-1313 | LCN APP node support is added to Trace. | | |
| RTRACE-1314 | The Network View was not working for multi VLAN configurations. | | |
| RTRACE-1315 | Change Description column size was not big enough to display whole information. | | |
| RTRACE-1336 | The non-numeric value was not being displayed as NaN. | | |

| JIRA/SIEBEL PAR Reference | Issue - Description/Recovery/Workaround |
|---------------------------------|--|
| RTRACE-1316 | HPM DEVCTL was not showing the logic inside it. |
| RTRACE-1332 | The Null blocks were also displayed in logic point type of HPM node. |
| RTRACE-1333 | PTDESC parameter was not in the frequent parameter list. |
| RTRACE-1317 | CL was pointing to comment lines, which described the tag, was showing as an anomaly. |
| RTRACE-1335 | CL points to hard point (NMxxHPMxx) and even if this hard point was present, it still used to display the point as "not present." |
| RTRACE-1334 | In TPS system, multiple writes to same parameter anomaly for HPM logic point type is corrected. |
| RTRACE-1320 | TPS SMM points configured beyond 255 were not displayed. |
| RTRACE-1318 | Display reference was not getting resolved for few tag references. |
| RTRACE-1319 | Trace migration was failing due to scheduling of reports in R120. |
| RTRACE-1176 | Trace application URL redirection issue has been resolved. Now, SPA application URL can be opened from same server node. |
| RTRACE-1297 | Port 80 is enabled and Trace is available only on port 443. |
| RTRACE-1338 | As Borregard was setup in a different culture (Norwegian environment), data collection was not happening as there is difference in date and decimal formats. Post this fix, the issue is resolved across all the cultures. |
| RTRACE-1337 | Service registry was not updated so issue came during patch 1 installation. |
| RTRACE-1416 | FSC and Experion external references were not getting displayed. |

| JIRA/SIEBEL PAR Reference | Issue - Description/Recovery/Workaround |
|---------------------------|--|
| RTRACE-1417 | The data collection was failing in Change Management due to duplicate records in Display Reference. |
| RTRACE-1418 | The data collection was failing in Defect Management due to the large size of defect tracking ID field and the column size was less. |
| RTRACE-1419 | In the Spares filter, under the "Reserved By" and "Types" fields, if multiple values were part of the search result, only the first one appeared. |
| RTRACE-1420 | The Global Tag Search was not displaying the hyperlinks for few tags even though the data was present. |
| RTRACE-1421 | TPS: For HPM REGPV, parameters namely CALCEXP, C1, C2, C3, and C4 were mismatching. In HPM CLs, under Reference Connections tab, references between point and CL was not appearing. |
| RTRACE-1422 | TPS: For AM REGLATRY point connections, CDS parameters were not appearing. For AM CUSTOM point, CDS parameters types such as, Entity and Connections were not displayed |
| RTRACE-1423 | TPS: In AM CL, the EXTERNAL tags which come after ampersand (&) in continuation lines are not being displayed as references between AM CL and tags. TPS: In AM REGLATRY, for multiple point connections has same parameter name such as, PISRC[1]. Now, each point parameter name is distinct. The parameters are now appearing as PISRC[1], PISRC[2], PISRC[3], and so on. |
| RTRACE-1424 | The IAA pdf files were not getting generated. |
| RTRACE-1425 | If more than 10,000 PHD tags were configured, there were few references which were still missing. |
| RTRACE-1426 | The duplicate information was appearing in the final result set. |

| JIRA/SIEBEL PAR Reference | Issue - Description/Recovery/Workaround |
|---------------------------------|---|
| RTRACE-1427 | <p>For generating a report for systems apart from TPS and Experion, the complete list of external references was not appearing.</p> <p>For generating a report for systems apart from TPS and Experion, the complete list of alias references was not appearing.</p> |
| RTRACE-1428 | <p>Earlier, for PHD system, users could only add single dependent TPS system. Users can now add multiple dependent TPS systems from the Add System Configuration page.</p> |
| RTRACE-1429 | <ul style="list-style-type: none"> (i) For PHD Shadow Server topology, PHD references for TPS system were not displayed even though the system is selected as TPS Dependent. (ii) The PHD references were not appearing when multiple RDIs were configured with same name for different source collectors. Now, all the RDI names are unique and PHD references are appearing. (iii) Earlier, the PHD references for RDM (one of the RDI types) communication protocol were not displayed. With this fix, the PHD references are displayed successfully. |
| RTRACE-1430 | <p>Even if the PHD was linking to various TPS system tag references, the PHD was configured to display only one TPS system at a time in the user interface.</p> |
| RTRACE-1431 | <p>The invalid point references in CL Engineering Anomaly were interpreted and displayed as anomaly (commented lines) for TPS, even though they are false anomalies.</p> |
| RTRACE-1432 | <p>The invalid point references in Display Engineering Anomaly were interpreted and displayed as anomalies for Hardware points and System displays, even though they are false anomalies.</p> |
| RTRACE-1433 | <p>For TPS AM points, the generic CL and CDS references were not being displayed.</p> |
| RTRACE-1434 | <p>The Network View was showing duplicate systems in all the switches and the port numbers were duplicated.</p> |
| RTRACE-1435 | <p>The OPCG references via RDM between Experion and TPS were not working.</p> |

| JIRA/SIEBEL PAR Reference | Issue - Description/Recovery/Workaround |
|---------------------------------|---|
| RTRACE- 1436 | In the Change Detection page, on applying individual filters such as, Unacknowledged, Acknowledged, or Suppressed, the count was not matching with the actual filter records. |
| RTRACE- 1437 | If Trace is installed on a server with multiple drives, the System Audit folder gets installed on non-C drive, which affected the saving feature in Global Settings. |

5 JIRA PARs

5.1 Resolved PARs

| Sl. No. | Resolved PARs |
|-------------|--|
| RTRACE-1073 | Validation for a failed system is no more getting deleted before confirmation. |
| RTRACE-1050 | In Flex Station, icons are appearing in the Network View. |
| RTRACE-1097 | The page does not time out before package is imported in Central mode. |
| RTRACE-1045 | Duplicate records are no longer appearing in the list. |
| RTRACE-1048 | Spaces, underscore, and hyphen are allowed. |
| RTRACE-978 | Channel number is included in the exported spare csv. |
| RTRACE-1069 | Hardware View chassis of Triconex is now displayed in vertical order. |

5.2 Known Issues

| Sl. No. | Known Issues |
|-------------|---|
| RTRACE-1068 | [TPS]: In Change Detection page, even though there are no changes in CL, it was appearing as "Updated" in change detection. |

6 Siebel PARs

6.1 Resolved PARs

| Sl. No. | Resolved PARs |
|-----------|---|
| 1-9PKK1PU | In external reference report, the container column was showing CM data instead of showing container data. |
| 1-9QOTJVD | Duplicate records were appearing for object names in global search. |
| 1-9BA88AZ | Earlier, the records were fetched only for exact matches in paramquery search. But now, records are successfully fetched even if the typed information in the search bar is similar to actual record information. |
| 1-9MBRIVX | Some of the configurable parameters in Experion blocks were missing. |

6.2 Known Issues

| Sl. No. | Known Issues |
|-----------|--|
| 1-9PKK1PM | SM block connections are missing for all FLDs. |
| 1-8XXA43F | Description: Unable to save the System Performance Settings in Global Advanced settings Workaround: Some files get copied to D drive. So, go to D drive and copy the files manually to C drive. |
| 1-9NQHKLD | Workaround- If IAA reports are vanished post-data collection failure. The snapshot can be scheduled by selecting IAA to have the system performance report generated. |

7 Notices

Trademarks

Experion®, PlantScape®, SafeBrowse®, TotalPlant®, and TDC 3000® are registered trademarks of Honeywell International, Inc.

OneWireless™ is a trademark of Honeywell International, Inc.

Other trademarks

Microsoft and SQL Server are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.

Trademarks that appear in this document are used only to the benefit of the trademark owner, with no intention of trademark infringement.

Third-party licenses

This product may contain or be derived from materials, including software, of third parties. The third party materials may be subject to licenses, notices, restrictions and obligations imposed by the licensor.

The licenses, notices, restrictions and obligations, if any, may be found in the materials accompanying the product, in the documents or files accompanying such third party materials, in a file named third_party_licenses on the media containing the product, or at <http://www.honeywell.com/ps/thirdpartylicenses>.

Documentation feedback

You can find the most up-to-date documents on the Honeywell Process Solutions support website at:

<http://www.honeywellprocess.com/support>

If you have comments about Honeywell Process Solutions documentation, send your feedback to:

hpsdocs@honeywell.com

Use this e-mail address to provide feedback, or to report errors and omissions in the documentation. For immediate help with a technical problem, contact your local Honeywell Process Solutions Customer Contact Center (CCC) or Honeywell Technical Assistance Center (TAC).

How to report a security vulnerability

For the purpose of submission, a security vulnerability is defined as a software defect or weakness that can be exploited to reduce the operational or security capabilities of the software.

Honeywell investigates all reports of security vulnerabilities affecting Honeywell products and services.

To report a potential security vulnerability against any Honeywell product, please follow the instructions at:

<https://honeywell.com/pages/vulnerabilityreporting.aspx>

Submit the requested information to Honeywell using one of the following methods:

Send an e-mail to security@honeywell.com.

or

Contact your local Honeywell Process Solutions Customer Contact Center (CCC) or Honeywell Technical Assistance Center (TAC) listed in the “Support” section of this document.

Support

For support, contact your local Honeywell Process Solutions Customer Contact Center (CCC). To find your local CCC visit the website, <https://www.honeywellprocess.com/en-US/contact-us/customer-support-contacts/Pages/default.aspx>.

Training classes

Honeywell holds technical training classes that are taught by process control systems experts. For more information about these classes, contact your Honeywell representative, or see <http://www.automationcollege.com>.

Honeywell Process Solutions

1250 W Sam Houston Pkwy S #150, Houston,
TX 77042

Honeywell House, Skimped Hill Lane
Bracknell, Berkshire, RG12 1EB

Building #1, 555 Huanke Road, Zhangjiang
Hi-Tech Park,
Pudong New Area, Shanghai, China 201203
www.honeywellprocess.com

HTDOC-X438-EN-121 PATCH 2
December 2018
© 2018 Honeywell International Sàrl

Honeywell