

Tai-Ji PID

R310.2

Software Change Notice

Revision Date: December 5, 2019

Document ID: TJPID-SCN-310.2

Notices and Trademarks

© Honeywell International Sarl March 5, 2020 3:09 PM. All Rights Reserved.

This document is the confidential and proprietary information of Honeywell. Reproduction and distribution of these materials without the express written consent of Honeywell is strictly forbidden.

While this information is presented in good faith and believed to be accurate, Honeywell disclaims the implied warranties of merchantability and fitness for a purpose and makes no express warranties except as may be stated in its written agreement with and for its customer.

In no event is Honeywell liable to anyone for any direct, special, or consequential damages. The information and specifications in this document are subject to change without notice.

These commodities, technology, or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law prohibited.

This product may contain or be derived from materials, including software, of third parties. The third party materials may be subject to licenses, notices, restrictions and obligations imposed by the licensor. The licenses, notices, restrictions and obligations, if any, may be found in the materials accompanying the product, in the documents or files accompanying such third party materials, in a file named `third_party_licenses` on the media containing the product.

Honeywell, Experion, Profit, Business FLEX, and TotalPlant are US registered trademarks of Honeywell International Inc.

Other brand or product names are trademarks of their respective owners.

Honeywell Process Solutions
1860 West Rose Garden Lane
Phoenix, AZ 85027 USA
1-800 822-7673

Documentation feedback

You can find the most up-to-date documents on the Honeywell Process Solutions support website at:

<http://www.honeywellprocess.com/support>

If you have comments about Honeywell Process Solutions documentation, send your feedback to:

hpsdocs@honeywell.com

Use this email address to provide feedback, or to report errors and omissions in the documentation. For immediate help with a technical problem, contact your local Honeywell Process Solutions Customer Contact Center (CCC) or Honeywell Technical Assistance Center (TAC) listed in the “Support and other contacts” section of this document.

How to report a security vulnerability

For the purpose of submission, a security vulnerability is defined as a software defect or weakness that can be exploited to reduce the operational or security capabilities of the software.

Honeywell investigates all reports of security vulnerabilities affecting Honeywell products and services.

To report a potential security vulnerability against any Honeywell product, please follow the instructions at:

<https://honeywell.com/pages/vulnerabilityreporting.aspx>

Submit the requested information to Honeywell using one of the following methods:

- o Send an email to security@honeywell.com.
- OR
- o Contact your local Honeywell Process Solutions Customer Contact Center (CCC) or Honeywell Technical Assistance Center (TAC) listed in the “Support and other contacts” section of this document.

Support and other contacts

For support and other contact details, go to <https://www.honeywellprocess.com/en-US/contact-us/customer-support-contacts/Pages/default.aspx>.

Table of Contents

1	Introduction	5
1.1	About the document	5
1.2	About the Hotfix	5
1.2.1	Limitations	5
1.2.1.1	Known Issues.....	5
1.3	Before you begin	5
1.3.1	Prerequisites	5
1.3.2	Verify the present version on the node.....	6
2	installation	7
2.1	Installing Taiji PID R3.10.2.1	7
2.1.1	To validate the installation.....	7
3	Uninstallation	8
3.1	Removing the Hotfix from Taiji PID Typical	8
4	Issues Resolved in 3.1.0.207	9

1 Introduction

1.1 About the document

The Software Change Notice describes the prerequisites, resolved PARs, applicable nodes, and steps to install/uninstall the Hotfix. Additionally, the SCN contains information about the change impact and additional information for this Hotfix. The latest version of this SCN is always available on the Honeywell Process Solutions website.

1.2 About the Hotfix

This Hotfix addresses problems and offers improvements requested since the release of Taiji PID R310.

This Hotfix resolves the following issues/Enhancements.

PAR	Description of problem
1-7X3V3JB	TaiJi browse for OPC tags does not provide the correct OPC tag name when importing data from OPC HDA
1-87RSMGI	TaiJi tuning is incorrect
1-8XU2LA5	When PID loop is taken for Step Testing, preset SP test limits defaults to SP Limits

1.2.1 Limitations

1.2.1.1 Known Issues

PAR	Description of problem
RCPM-7000	For any loop (closed\open\cascade\mimo), when we read the scale values either from DCS OR from config file:: Then in diagnosis tab, SP\OP test limits are resetting back to original.

1.3 Before you begin

1.3.1 Prerequisites

This Hotfix is a cumulative release of Taiji PID R 3.1.0.207 and Taiji PID R3.10.2.1. The Hotfix must be installed on a node on which any one of the following applications are installed.

- Taiji PID R 3.1.0.206

- Taiji PID R 3.1.0.207

1.3.2 **Verify the present version on the node**

To verify the present version on the node, perform the following steps.

1. Open **Add Remove Programs**.
2. Verify that the installed version of Taiji PID is 3.1.0.206 or 3.1.0.207.

2 installation

2.1 Installing Taiji PID R3.10.2.1

If you have Taiji PID R310 with a **Typical Installation**, you must perform the following installation procedure.

To install the Taiji PID R3.10.2.1 (For both Typical and Custom)

Step	Action
1	Right-click TaijiPID_R3.10.2.1.exe and click Run As Administrator . The welcome screen appears. Note: Make sure that you have closed all running TaijiPID applications before you start installing Taiji PID R3.10.2.1.
2	Click Next . Follow the on-screen instructions to complete the installation.

2.1.1 To validate the installation

After the installation, verify the following entry "**Honeywell TaiJi Patch**" and the version is **3.10.2.1** appears in Add Remove Programs.

3 Uninstallation

3.1 Removing the Hotfix from Taiji PID Typical

To remove the Hotfix follow the below steps.

1. Close all running Taiji PID applications before removing the Hotfix.
2. Go to Control Panel and Navigate to **Add Remove Programs**.
3. Select **Honeywell Taiji Patch**, with the version **3.10.2.1**, and then click **Uninstall**.
4. Proceed with subsequent wizards.

4 Issues Resolved in 3.1.0.207

This Hotfix addresses problems and offers improvements requested since the release of Taiji PID R310. The Taiji PID R3.1.0.207 Hotfix resolves the following issues/Enhancements.

PAR	Subsystem	Description of the Problem
1-9902789237	Taiji PID Web service	During model identification CPM won't report if there's an error -shows wrong result.
1-9902789433	Taiji PID	OPC Tag browser will show tags only if we use the wildcard